

SR 3.02 Watertight Integrity of Hull

Special Regulations, Part 1, Section 3, Structural Features, Stability

1. Issue

Australian Sailing's clauses for keel inspection are inconsistent with <u>World Sailing's Offshore Special Regulations (OSR).</u>

2. Recommendation

The National Safety Committee recommend Australian Sailing amend the Special Regulations by aligning its clauses regarding keel inspection with those in World Sailing Offshore Regulation 3.02.

3. Reasons

- 1. To bring the Special Regulations into alignment with World Sailing's OSR by adopting the clauses relating to keel inspections.
- 2. Structural inspections are set down by World Sailing and Australian Sailing is obliged to conform.
- 3. Given the changes are administrative, public consultation should not be required.

AUSTRALIAN SAILING

CHANGES TO
Australian Sailing Special Regulations

Issued on 27 March 2025 Effective from 28 May 2025

PART 1, SECTION 3 STRUCTURAL FEATURES, STABILITY

Regulations 3.02 Watertight Integrity of Hull

Delete the text that has been struck out and insert the text that has been underlined.

3.02.4 Effective 1 January 2022: Structural Inspection – Consult 1 2 3 the owner's manual for any instructions for keel bolt checking and re-tightening. The following inspection to be conducted by a qualified person externally with the boat out of the water. Check that there are no visible stress cracks particularly around the keel, hull/keel attachment, hull appendages and other stress points, inside the hull, backing plates, bolting arrangements and keel floors. (See Appendix C – Model Keel and Rudder Inspection Procedure)

3.02.5 Effective 1 January 2022: Evidence of a structural inspection in accordance with 3.02.4 within 24 months

1 2 3

before the start of the race or after a grounding whichever is the later.

3.02.6 Effective 1 January 2022: Inspection after Grounding – an appropriately qualified person shall conduct an internal and external inspection after each unintentional grounding.

1 2 3